

Vacuum gauge 100 -kPa, with nut / -30 inHg, 3101602



- Analogue indicator, springjoint – lever system
- The instruments include nut for installation on a panel

General

Material	ABS, CuZn, PMMA
Medium	Vacuum
Weight	90 g

Electrical data

Accuracy, electrical	2,5 % FS
----------------------	----------

Signal function

Signal range	0 – 100 -kPa
--------------	--------------

Dimensional drawings

